

MANDATORY SERVICE BULLETIN**NUMBER:** SB-018**REVISION:** A**DATE:** 7/31/2009**SUBJECT:** FUEL SYSTEM; MANDATORY CHAFE PROTECTION ADDITION TO MAIN CABIN FUEL LINES**SUMMARY****RECURRENT REQUIREMENTS**

No recurrent requirements associated with this Mandatory Service Bulletin.

BACKGROUND

Quest is mandating the addition of chafe protection to the Main Cabin Fuel Lines.

ACTION

Follow the instructions attached to this Service Bulletin to add adequate chafe protection to the Main Cabin Fuel Lines.

EFFECTIVITY

KODIAK 100 Series Aircraft, Serial Numbers 100-0001 through 100-0019

AFFECTED PARTS

KODIAK PART AFFECTED:

- 100-828-4631 Fuel Line
- 100-828-4660 Fuel Line
- 100-828-4659 Fuel Line
- 100-828-4656 Fuel Line
- 100-828-4655 Fuel Line
- 100-828-4653 Fuel Line
- 100-270-3012 Stringer

REPLACEMENT PART FOR AIRCRAFT RECORDS:

- N/A

COMPLIANCE

This Mandatory Service Bulletin must be completed no later than the next 100 flight hours or Annual Service, whichever comes first.

INDUSTRY SUPPORT INFORMATION

None

MANPOWER

This procedure will take approximately 3 hours to complete.

COMPLETION

Update the KODIAK Maintenance Log Books.

WARRANTY INFORMATION

This modification is warranty reimbursable for the manpower listed above after Quest Aircraft has been notified of your completion.

Quest Aircraft Company, LLC
© Copyright 2008
All Rights Reserved

No part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Quest Aircraft Company, LLC.





IMPORTANT SERVICE BULLETIN


**FUEL SYSTEM; Mandatory Chafe Protection
Addition to Main Cabin Fuel Lines**

FIELD MODIFICATION INSTRUCTIONS

FUEL SYSTEM; Mandatory Chafe Protection Addition to Main Cabin Fuel Lines

Task	Instruction	Image
1	<p>Remove the kick panel and paneling in accordance with the KODIAK 100 Maintenance Manual.</p> <p>Note: Do be sure to unplug the headphone jacks in the lining and the heaters located in the kick panel.</p> <p>Remove the necessary insulation in order to access the base of the fuel lines.</p>	
2	<p>After the insulation has been removed, locate the stringer that is depicted in RED. See Figure 2.</p>	 <p style="text-align: center;">Figure 2 - Stringer Location (RED)</p>
3	<p>Inspect the fuel lines in the area around the stringer for any sign of damage due to chafing. If damage is found, determine whether it is slight surface rubbing or if the fuel line is significantly damaged. If the fuel line is significantly damaged, it will need to be replaced per the KODIAK 100 Maintenance Manual.</p>	

FUEL SYSTEM; Mandatory Chafe Protection Addition to Main Cabin Fuel Lines

Task	Instruction	Instruction
4	<p>Irrespective of evidence of chafing, chafe protection shall be installed. Cut a piece of CAT Track™ 6 inches long and install on the stringer at the fuel lines as shown.</p>	
7	<p>Reinstall the insulation. Plug in the heaters and head phone jacks. Install the side panels in accordance with the KODIAK 100 Maintenance Manual.</p>	
8	<p>Repeat steps 1-7 on the opposite side of the fuselage.</p>	
9	<p>Note the work performed in the KODIAK 100 Log Books.</p>	