

MANDATORY SERVICE BULLETIN**REVISION RECORD**

| REV | PAGE | CHANGE DESCRIPTION |
|-----|------|--------------------|
| 00 | All | Initial Release |

SUBJECT

Replacement of Japanese translated placards with typographic errors and missing content for Japanese registered airplanes.

EFFECTIVITY

Original Effective Date: 01/29/2019

Serial Range: 100-0001 thru 100-0204, for aircraft that were Japanese registered prior to the effective date of this Mandatory Service Bulletin.

SUMMARY

The accompanying Field Service Instruction provides procedures for the installation and/or replacement of required placards on Japanese Registered airplanes equipped with TKS and Japanese Registered airplanes not equipped with TKS.

| DOCUMENT NUMBER | TITLE |
|-----------------|---------------------------------------|
| FSI-150 | Japanese Registered Airplane Placards |

COMPLIANCE

This Mandatory Service Bulletin must be complied with on or before the next scheduled maintenance.

SPECIAL INSTRUCTIONS

None.

CREDIT AND WARRANTY INFORMATION

For compliance completed on or before June 1, 2019, Quest will supply one (1) service kit QK100-0081 per Japanese registered airplane at no cost and reimburse up to one (1) hour of labor associated with completing the procedures in FSI-150. Contact Quest Customer Service to order the service kit. Refer to our web site at customercare.questaircraft.com for warranty claim reimbursement instructions.

Quest Aircraft Company
1200 Turbine Drive
Sandpoint, Idaho 83864

Quest Customer Service
Toll Free: 1 (866) 263-1112
Email: customerservice@questaircraft.com