

MANDATORY SERVICE BULLETIN

REVISION RECORD

REV	DATE	PAGE	CHANGE DESCRIPTION
00	12/18/18	ALL	Initial release.

SUBJECT

Throttle-Control Bracket Thread Engagement

EFFECTIVITY

Original Effective Date: 01/29/2019

Serial Range: 100-0001 through 100-0258

SUMMARY

For airplane serial numbers 100-0001 through 100-0258, nuts used on the throttle-control bracket may not provide the mating studs with sufficient thread engagement. Replace the nuts in accordance with the FSI document listed in the following table.

DOCUMENT NUMBER	TITLE
FSI-164	Throttle-Control Bracket Thread Engagement

COMPLIANCE

This Mandatory Service Bulletin must be complied with at or before the next annual inspection.

CREDIT AND WARRANTY INFORMATION

Quest Aircraft Company will supply one (1) service kit at no cost and reimburse up to 0.5 hour of labor costs for airplanes under warranty. For airplanes no longer under warranty, only the service kit will be supplied at no cost. Contact Quest Customer Service to order the kit. Refer to Quest's technical publications portal at <http://customercare.questaircraft.com/portal-login/> for warranty claim reimbursement instructions.

Quest Aircraft Company
1200 Turbine Drive
Sandpoint, Idaho 83864

Quest Customer Service
Toll Free: 1 (866) 263-1112
Email: customerservice@questaircraft.com