

MANDATORY SERVICE BULLETIN

REVISION RECORD

| REV | DATE | PAGE | CHANGE DESCRIPTION |
|-----|----------|------|--------------------|
| 00 | 08/27/19 | ALL | Initial release. |

SUBJECT

Reduced Fuel-Transducer Orifice

EFFECTIVITY

Original Effective Date: 09/30/2019

Serial Range: 100-0001 through 100-0274

SUMMARY

An improved fuel-filter fitting has been designed with a reduced orifice that will restrict fuel flow to the fuel-pressure transducer, minimizing fuel loss if a leak occurs. This new fitting features a notch in its wrenching surface for convenient identification. The Field Service Instruction listed in the following table provides procedures for installation of this new fitting.

| DOCUMENT NUMBER | TITLE |
|-----------------|---------------------------------|
| FSI-167 | Reduced Fuel-Transducer Orifice |

COMPLIANCE

This Mandatory Service Bulletin must be complied with at or before the next annual inspection.

CREDIT AND WARRANTY INFORMATION

Quest will supply one (1) service kit at no cost and reimburse up to a half (0.5) hour of labor costs for airplanes under warranty. For airplanes no longer under warranty, only the service kit will be supplied at no cost. Contact KODIAKCARE to order the kit. Refer to Quest's technical publications portal at <http://customercare.questaircraft.com> for warranty claim reimbursement instructions.

Quest Aircraft Company
1200 Turbine Drive
Sandpoint, Idaho 83864

KODIAKCARE
Toll Free: 1 (866) 263-1112
Email: kodiakcare@questaircraft.com