

RECOMMENDED SERVICE LETTER**NUMBER:** SL-006**DATE:** 04/21/2009**SUBJECT:** FLIGHT CONTROLS; 22 Degree Elevator Change**SUMMARY**

QUEST AIRCRAFT RECOMMENDS THAT EACH OPERATOR EXAMINE THIS SERVICE LETTER IMMEDIATELY.

CONCURRENT REQUIREMENTS

None

BACKGROUND

The KODIAK 100 was recently modified to allow 22 degrees of elevator travel. This change to the flight controls was made to allow for additional aircraft options and configurations such as cargo pod and floats.

ACTION

The 22 degree elevator change is required to be completed by a Quest Field Service representative.

EFFECTIVITY

KODIAK 100 Series Aircraft, serial numbers 100-0001 through 100-0003.

COMPLIANCE

This Service Letter must be complied with on or before the next scheduled maintenance interval not to exceed the next 100 hour inspection.

INDUSTRY SUPPORT INFORMATION

N/A

MANPOWER

N/A

COMPLETION

N/A

RECOMMENDED SERVICE LETTER

RECOMMENDED SERVICE LETTER

Quest Aircraft Company, LLC
© Copyright 2008
All Rights Reserved

No part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Quest Aircraft Company, LLC.