

MANDATORY SERVICE BULLETIN**NUMBER:** SB-002 Amendment 1**DATE:** 10/03/2008**SUBJECT:** FUEL SYSTEM; Mandatory Fuel Drain Valve Replacement**SUMMARY**

QUEST AIRCRAFT RECOMMENDS THAT EACH OPERATOR COMPLY WITH THIS MANDATORY SERVICE BULLETIN IMMEDIATELY.

ACTION:

This amendment is to specify serial numbers affected by the Mandatory Service Bulletin released 09/16/2008. (SB-002 Fuel System; Mandatory Fuel Drain Valve Replacement)

Serial numbers affected by SB-002:

- SN-001
- SN-002
- SN-003
- SN-004
- SN-005

No action required for this Mandatory Service Bulletin Amendment.

If you have any questions, please contact Quest Customer Service at (208) 263-1111.

MANDATORY SERVICE BULLETIN***MANDATORY SERVICE BULLETIN***

Quest Aircraft Company, LLC
© Copyright 2008
All Rights Reserved

No part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Quest Aircraft Company, LLC.