

MANDATORY SERVICE BULLETIN**NUMBER:** SB-006**DATE:** 4/7/2009**SUBJECT:** LANDING GEAR; MAIN GEAR CROSS TUBES INSPECTION**SUMMARY****RECURRENT REQUIREMENTS**

No recurrent requirements associated with this Mandatory Service Bulletin.

BACKGROUND

During a recent receiving inspection, Quest Aircraft discovered inner diameter variance in concentricity measurements in the main gear cross tubes. Quest is requiring a one-time cross tube inspection. This inspection will need to be completed by a Quest Field Representative.

REQUIRED ACTION

Quest is requiring a one-time Main Gear Cross Tube Inspection using ultrasonic nondestructive testing. This inspection can only be completed by a Quest Field Service Representative. Please contact Quest Customer Service to schedule an inspection date.

EFFECTIVITY

Serial Numbers 100-0001 through 100-0009

COMPLIANCE

This inspection needs to be accomplished at or before the next annual inspection.

INDUSTRY SUPPORT INFORMATION

N/A

MANPOWER

None. This inspection will be completed by a qualified Quest Field Service Representative.

COMPLETION

Upon completion of this Service Bulletin, enter the maintenance performed into the appropriate aircraft maintenance records.

MANDATORY SERVICE BULLETIN***MANDATORY SERVICE BULLETIN***

Quest Aircraft Company, LLC
© Copyright 2008
All Rights Reserved

No part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Quest Aircraft Company, LLC.